

# 4S SPRING SETS XRAY T4

## LINEAR SPRINGS




C=2.9

C=2.8



C=2.7

C=2.6



C=2.5



C=2.3

## PROGRESSIVE SPRINGS



#308263

C=2.3~2.6



#308264

C=2.5~2.8

**4S - SUPER SHORT SHOCK SPRINGS**  
**INDIVIDUALLY MEASURED, CONTROLLED, INSPECTED**  
**PROGRESSIVE AND LINEAR SETS**  
**PERFECT SPRING MATCH-UPS**  
**LASER ENGRAVED FOR EASY IDENTIFICATION**

**LASER  
ENGRAVED**



Developed, designed & styled by  
Dipl. Eng. Juroj Hudy,  
Chief Designer, XRAY

